



BRUHATH BENGALURU MAHANAGARA PALIKE
Devarachikkanahalli Road, Begur, Bengaluru – 560068

NO.AEE/BEG/PR/460/2025-26

Date:30.06.2025

Office of the Assistant Executive Engineer
B.B.M.P Begur Sub – Division
Bommanahalli Zone
Bangalore, Karnataka

Sub:- Regarding Issue of School building safety certificate.
Ref:- Your Request lettr Dated: 20.06.2025

With reference to the above subject, we here by SAMSIDH INTERNATIONAL SCHOOL No.33/58/4, koodlu Village, Begur Hobli Bangalore-68. Singasandra Ward No.191, Has been inspected on Date.20.06.2025 the building is comprises R.C.C Framed structure of Ground Floor, First Floor, Second Floor, Third Floor & Fourth Floor, the building has been constructed in the year 2014-15, In the Building General Safety, Light, Air and Ventilation are seems to be adequate.

The Structural safety should be got certified from the private Structural Experts, Since the structural Analysis Department is not exisis in the Bruhath Bengaluru Mahanagara Palike.

Your faithfully
[Signature]
Assistant Executive Engineer
Assistant Executive Engineer
Begur Sub Division
BEGUR SUB DIVISION
BBMP

To,
M//Vasa Shrinivas Rao
SAMSIDH INTERNATIONAL SCHOOL
No.33/58/4, Koodlu Village
Singasandra Ward No.191
Begur Hobli, Bangalore-68