



**BRUHATH BENGALURU MAHANAGARA PALIKE**  
Devarachikkanahalli Road, Begur, Bengaluru – 560 068.

No.AEE/BEG/PR/460/2022-2023

Date: 07.02.2023

Office of the Assistant Executive Engineer  
B.B.M.P Begur Sub-Division  
Bommanahalli Zone  
Bangalore, Karnataka


**Sub:-** Regarding issue of School building safety certificate.

**Ref :-** Your Request letter Dated: 02.02.2023

\*\*\*\*\*

With reference to the above subject, we here by Samsidh Mlzs School, No. 33/58/4, Koodlu Village, Begur Hobli, Bangalore – 68. Singasandra Ward No.191, Has been inspected on Date:07.02.2023 The building is comprises R.C.C Framed structure of Ground Floor, First Floor, Second Floor, Third Floor & Forth Floor the building has been constructed in the year 2014-15. In the Building General safety, Light, Air and Ventilation are seems to be adequate.

The Structural safety Should be got certified from the Private Structural Experts. Since the structural Analysis Department is not exists in the Bruhath Bengaluru Mahanagara Palike.

  
Yours faithfully,  
ಶ್ರೀ ಎಂ.ಎಸ್. ಶ್ರೀನಿವಾಸ ರಾವ್  
Assistant Executive Engineer  
ಬೆಗುರು ಸಬ್-ಡಿವಿಷನ್  
BBMP

To,  
M//Vasa Shrinivas Rao.  
Samsidh Mlzs School,  
No. 33/58/4, Koodlu Village,  
Singasandra Ward No.191,  
Begur Hobli, Bangalore – 68.

SAMSIDH EDUCATIONAL SOCIETY  
  
Authorised Signatory