Annexure D

BUILDING SAFETY CERTIFICATE

NO.16			Dated: 24-08-2024					
It is certified that the	existing build	ding	St. JOSEPI	I PU	BLIC SCHOO	<u>DL</u> (nar	ne of the	· ·
building or premises) at .	Survey No. 3	3, Rachanapal	li, ANANT	APU!	R-515004		::	
(ad	ldress) is hav	ving block(s)/l	Floor(s) as	per	details below	r.		
Detail of Block(s) in	Block	Block	Block		Block	Block	Block	
school	(1)	(2)	(3)	1	(4)	(5)	(6)	
No. of Floor(s) in the Block	Ground & 1st Floor							
The building is owned/or	cupied by	St. Joseph	Education	ıal S	ociety		(năme	
of the Institution) have of							•	
Building code Rules, and	d verified by	the officers of	concerned	of	Engineerin	g Assistant	(Name of	
Department/ Govt.)	on23-0	8-2024 (date of	in	spection) —	in — the	presence	
of C Damodar Reddy, S	ndicate Naga	ır, ANANTAP	UR	:::::::	:::	ame and a	dresses of the	1e
Manager/Secretar or his	s representa	tive) and tha	at the build	ding/	premises is	fit for occup	ancy for	
running school with effect						years in ac	cordance	
with rule and subject to compliance of the specific conditions as appended.								
Issued on 24-08-20	24 ãť	11:30 Å	M by					
						D.	Sandy	
Engineering Assistant								
Rachanapalli Grama Sachivalaym Signature with Seal : Anantapur Rural (Mdl).								
			Olgi	iaiui			bra Prayer	1
							ening Assi	
,		N	ame & Add	Iress	of Departme	ent/ Office: R	sehan pol	Li.
	-				•	P.R Dep	yan & Bg.	